


PORCA REDUÇÃO



SIZE	1/4x1/8		3/8x1/8		3/8x1/4		1/2x1/8		1/2x1/4		1/2x3/8		3/4x1/8		3/4x1/4		3/4x3/8		3/4x1/2	
	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in
L	17	0.67	17.5	0.69	17.5	0.69	22	0.87	22	0.87	22	0.87	23	0.91	23	0.91	23	0.91	23	0.91
H	12.5	0.49	12	0.47	12	0.47	16	0.63	16	0.63	16	0.63	17	0.67	17	0.67	17	0.67	17	0.67
W	17	0.67	21	0.83	21	0.83	25	0.98	25	0.98	25	0.98	30	1.18	30	1.18	30	1.18	30	1.18

SIZE	1x1/4		1x3/8		1x1/2		1x3/4		1-1/4x1/2		1-1/4x3/4		1-1/4x1		1-1/2x1/2		1-1/2x3/4		1-1/2x1	
	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in
L	27.5	1.08	27.5	1.08	27.5	1.08	27.5	1.08	30	1.18	30	1.18	30	1.18	30.5	1.20	30.5	1.20	30.5	1.20
H	20	0.79	20	0.79	20	0.79	20	0.79	21.5	0.85	21.5	0.85	21.5	0.85	22	0.87	22	0.87	22	0.87
W	37	1.46	37	1.46	37	1.46	37	1.46	46	1.81	46	1.81	46	1.81	50	1.97	50	1.97	50	1.97

SIZE	1-1/2x1-1/4		2x3/4		2x1		2x1-1/4		2x1-1/2		2-1/2x1		2-1/2x1-1/4		2-1/2x1-1/2		2-1/2x2		3x1/2	
	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in
L	30.5	1.20	33.5	1.32	33.5	1.32	33.5	1.32	33.5	1.32	40	1.57	40	1.57	40	1.57	40	1.57	41	1.61
H	22	0.87	23.5	0.93	23.5	0.93	23.5	0.93	23.5	0.93	29	1.14	29	1.14	29	1.14	29	1.14	29	1.14
W	50	1.97	62	2.44	62	2.44	62	2.44	62	2.44	80	3.15	80	3.15	80	3.15	80	3.15	92	3.62

SIZE	3x3/4		3x1		3x1-1/4		3x1-1/2		3x2		3x2-1/2		4x1/2		4x3/4		4x1		4x1-1/4	
	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in	mm	in
L	41	1.61	41	1.61	41	1.61	41	1.61	41	1.61	41	1.61	45	1.77	45	1.77	45	1.77	45	1.77
H	29	1.14	29	1.14	29	1.14	29	1.14	29	1.14	29	1.14	31	1.22	31	1.22	31	1.22	31	1.22
W	92	3.62	92	3.62	92	3.62	92	3.62	92	3.62	92	3.62	118	4.64	118	4.64	118	4.64	118	4.64

SIZE	4x1-1/2		4x2		4x2-1/2		4x3	
	mm	in	mm	in	mm	in	mm	in
L	45	1.77	45	1.77	45	1.77	45	1.77
H	31	1.22	31	1.22	31	1.22	31	1.22
W	118	4.64	118	4.64	118	4.64	118	4.64